Outpak™
Slurry Solution

DIRECTIONS

Add 2.5 lbs of our Outpak Slurry Solution per every .25cu yards of liquid waste. Mix well with a shovel. Let it set for 30-40 min to completely solidify.

Note:
Liquid waste may require more Slurry Solution depending on solids content of material. For faster reaction, add more Slurry Solution to the mix.

Disposal:
The disposal of used material is based on nature of liquid absorbed, which should be a non-flowing gel and must comply with all local, state and federal environmental regulations.

HEALTH	1	VOC	0
FLAMMABILITY	0	REACTIVITY	0

Net Content: 2.5 lbs

Outpak.com

(208) 890-0383

Manufactured By: Gelmaxx
Distributed By: Outpak Washout System

8 58928 00407 1